Oil Field Environmental Incident Summary

Responsible Party: Missouri Basin Well Service, Inc

Well Operator: MISSOURI BASIN WELL SERVICE, INC.

Well Name: BRENNA SWD 1

Field Name: UNION CENTER Well File #: 90217

Date Incident: 2/15/2015 Time Incident: 15:15 Facility ID Number:

County: MCKENZIE Twp: 152 Rng: 96 Sec: 13 Qtr: SE NE

Location Description:

Submitted By: Joshua Staggs Received By:

Contact Person: Dave Wanner

PO BOX 458

BELFIELD, ND 58622

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

12 Barrels 10 Barrels 12 barrels

Oil Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/4/2015 Clean Up Concluded: 2/23/2015

Risk Evaluation:

None, the spill was all contained in the tank farm berm.

Areal Extent:

Potential Environmental Impacts:

None, the spill was all contained in the tank farm berm.

Action Taken or Planned:

Investigation by company HSE team will uncover who committed act to retrain them on double checking valves before leaving; also the company is looking into either adding more cameras on site or an attendant on site to deter negligence.

Wastes Disposal Location: Liquids will be disposed at the Knudston SWD owned by MBI Energy

Services in Fairfield, ND. The recovered solids will be disposed of at a

Designated Special Waste Landfill.

Agencies Involved:

Updates

Date: 2/16/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.